

Appendix B

STATE OF CALIFORNIA—ENVIRONMENTAL PROTECTION AGENCY

PETE WILSON, G.

CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD
LOS ANGELES REGION101 CENTRE PLAZA DRIVE
MONTEREY PARK, CA 91754-2156
(213) 266-7500
FAX: (213) 266-7600


May 20, 1998

Mr. Chris Stoker
Integrated Environmental Services, Inc.
3990 Westerly Place, Suite 210
Newport Beach, CA 92660TECHNICAL WORKPLAN, INSTALLATION OF TEMPORARY GROUNDWATER
MONITORING WELLS - BOEING C-6 FACILITY, LOS ANGELES, CALIFORNIA
(FILE NO. 100.315)

We have received and reviewed your Technical Workplan, Installation of Temporary Groundwater Monitoring Wells - Boeing C-6 Facility, Los Angeles, California, dated April 20, 1998. Our comments are as follows:

- 1) Include a contingency plan to collect and analyze soil samples if visible contamination, odors or PID readings indicate that contamination is present. Samples should be analyzed for the same suite of chemicals for which the groundwater is being tested.
- 2) Collect and analyze a soil sample from the capillary fringe in each boring. Samples should be analyzed for the same suite of chemicals for which the groundwater is being tested.
- 3) The workplan indicates that the annulus above the bentonite sanitary seal will be left open. The annulus must be filled should visible contamination, odors or PID readings indicate that soil contamination is present.

Should you have any questions regarding the above, please contact Hugh Marley at (213) 266-7669.


J.E. ROSS, Unit Chief
Site Cleanup Unitcc: Ms. Karen Baker, DTSC, Long Beach
Ms. Debbie Oudiz, Office of Scientific Affairs
Mr. Mario Stavale, Boeing Realty Corporation
Mr. Jeff Dhont, Federal EPALc'd
5/26/98

28